

ASSEMBLY INSTRUCTION

A



M6x40

B



x4 $\phi 6 \times \phi 18$


C



x4 M5

x1

STEP 1



STEP 2

