



Erratum TF2401

TBRV170-200-230



2



14x

4x20

28x

2



10x

4x20

20x

3

10x



4x20

10x

3

6x



4x20

6x

3A


WX

WX

WX

TBRV230
TBRV170
TBRV200

4x




4x

WX

4x40

12x

4/5



ER_TF2401_TBRV170;TBRV200;TBRV230_Va_1-1