


ASSEMBLY INSTRUCTION


A



M5

x1

B



M6x16

x4


C



$\phi 6 \times \phi 18$

x4

STEP 1



STEP 2

