




Assembly instruction 6252


20 min




TORX T20



Possible legs




BST_46



BST_53

Package BST_53

1X



BST_53

1X






Table top

**05-002007
RW20
5,0x25**



10X


**05-001808
POD 6**



10X

Package BST_46

1X



BST_46

1X






Table top

**05-002007
RW20
5,0x25**



16X

**05-001808
POD 6**




16X

Assembly instruction 6252

BST_53

Install the legs according to the specially marked holes



BST_46/96

Install the legs according to the specially marked holes

