


ASSEMBLY INSTRUCTION

A

M5

x1



B

M6*16

x4

C $\phi 6 * \phi 18 * 1.5$ x4

STEP 1



STEP 2

